

7/10/13 8, E.I.

READ AND LANIADO, LLP
ATTORNEYS AT LAW
25 EAGLE STREET
ALBANY, NEW YORK 12207-1901

(518) 465-9313 MAIN
(518) 465-9315 FAX
www.readlaniado.com

KEVIN R. BROCKS
DAVID B. JOHNSON
SAM M. LANIADO

RICHARD C. KING
HOWARD J. READ
Of Counsel

KONSTANTIN PODOLNY
PATRICK A. SILER

Via Electronic Delivery

July 2, 2013

Hon. Jeffrey C. Cohen
Acting Secretary
NYS Public Service Commission
Three Empire State Plaza
Albany, NY 12223-1350

Re: Case 10-T-0350 – Laser Northeast Gathering Company, LLC and DMP New York, Inc. – Order Granting Certificate of Environmental Compatibility and Public Need (Issued and Effective: February 22, 2011) – Certificate Conditions 1(z) and 1(s2).

Dear Acting Secretary Cohen:

Williams Field Services Company, LLC (on behalf of DMP New York, Inc. and Laser Northeast Gathering Company, LLC) (collectively “Williams”), attaches the most recent sound sampling survey conducted by Hoover and Keith, Inc. (the “June 2013 Survey”) in connection with the Dunbar Compressor Station. Bad weather and prior existing scheduling conflicts unavoidably delayed the conduct and completion of the June 2013 Survey.

The June 2013 Survey demonstrates that the mitigation measures that Williams has implemented has had a positive impact on levels at both residences and property lines. As shown in the June 2013 Survey and previous surveys, the Dunbar Compressor Station is well within the 40 dBA limit at existing residences imposed by the Commission in the captioned Certificate. Similarly, if the three season sound monitoring data is used to establish the ambient of 43.2 dBA for the purposes of complying with the Town Noise Control Code, there are no longer any exceedances at any of the property lines. If, however, the one season data is used to establish the ambient of 40.5 dBA for purposes of the Town Noise Control Code, then there remains one exceedance at Position 12. This property line location is situated at relatively high elevation in a wooded/brush area with no residents nearby. This slight exceedance is solely caused by the location of the

